: AFT BASE ASS'Y

: D3651041

: 30/10/2008

: N/A

D3651 REV.B

Customer

Tuesday, 16/09/2008 3:28:43 PM

Julie Lecoco

Process Sheet

Part Number

Material

Due Date

Drawing Number

Project Number

Drawing Revision

Drawing Name

Job Number : 42040 -

Estimate Number : 13043

P.O. Number

: 16/09/2008 This Issue

Prsht Rev. : NC

: 11 First Issue

: 39931 Previous Run

Written By Checked & Approved By

Comment

New Issue 07-09-27

: CU-DAR001 Dart Helicontes Services

S.O. No.

ECN 1113P 08-01-22 DD verofoed by: EC Est Rev:C ecn1162

08-04-02

: SMALL /MED FAB

DD verified by: EC

DD verified by: EC

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

1.0

PACKAGING 1

PACKAGING RESOURCE #1

Comment: PACKAGING RESOURCE #1

Pick Packing Kit

2.0

D3651043

Flange Weldment

Comment: Qty.: 1.0000 Each(s)/Unit Total: 5.0000 Each(s)

FLANGE ASSEMBLY B 40856

08/10/02

Each

3.0 D36511

Gasket

Comment: Qty.:

1.0000 Each(s)/Unit Total:

5.0000 Each(s)

42115

4.0

D36519

Inside Doubler



DOUBLER

1.0000 Each(s)/Unit 5.0000 Each(s) Total:

138



D365111 5.0

Comment: Qty.:

Comment: Qty.:

Gasket




5.0000 Each(s) 1.0000 Each(s)/Unit Total:

GASKET









2				
				*
	-	-	N	

Tuesday, 16/09/2008 3:28:43 PM Julie Lecocq

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: AFT BASE ASS'Y

Job Number: 42040

Part Number: D3651041

Job Number:



Seq. #:

Machine Or Operation:

Description:

B42117 (5)

D365113 6.0

Outside Doubler

Comment: Qty.:

1.0000 Each(s)/Unit

5.0000 Each(s)

DOUBLER CR3523402

RIVET

40

7.0

Total:



Comment: Qty.:

58.0000 Each(s)/Unit Total: 290.0000 Each(s)

min6302

R 08/40/0

SMALL FAB 1 8.0



Comment: 1-Assemble as per dwg D3651 2- Seal all mating surfaces and gaps using Proseal 700 fire wall sealant as per dwg D3651

Batch: M 109 415

3-install D3651-1 using 3M high per formance contact adhesive 1357 as per dwg D3651

Batch: 17 105 6 2 3

FF 08/10/03

9.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP



10.0

PACKAGING '

PACKAGING RESOURCE #1



identify with Dart part # using a fine point permanent marker and Stock

11.0

FINAL INSPECTION/W/O RELEASE




Comment FINAL INSPECTION/W/O RELEASE

Job Completion



MUF 08-10-03

,		
•		
	K.	



			•	